

金能科技股份有限公司一厂区污染 场地调查及风险评估报告 附件

编制单位：中国科学院南京土壤研究所

二〇一七年二月

表1 初步调查土壤分析结果汇总表 (金属) (单位, mg/kg)

样品编号	点位	采样深度 (m)	pH	铜 (Cu)	铬 (Cr)	镍 (Ni)	锌 (Zn)	铅 (Pb)	镉 (Cd)	钒 (V)	砷 (As)	汞 (Hg)
检出限			-	0.10	0.10	0.10	0.50	0.10	0.01	1.00	0.5	0.05
筛选值				10000	2500	300	10000	1200	150	250	20	14
1	S1	0.2	8.4	17.2	56.9	25.2	58.5	17.4	0.14	66	9.7	/
2	S1	1.0	8.7	-	-	-	-	-	-	-	-	-
3	S1	2.0	8.3	29.2	75.5	38.0	81.8	26.2	0.25	98	20.9	/
4	S1	3.0		-	-	-	-	-	-	-	7.2	-
5	S2	0.2	8.1	18.0	56.6	25.7	59.0	19.3	0.18	64	11.3	/
6	S2	1.0	8.6	31.7	83.2	42.1	89.2	29.2	0.30	106	20.7	/
7	S2	2.0	7.8	-	-	-	-	-	-	-	9.1	-
8	S3	0.5	8.1	17.4	57.3	24.7	60.0	18.8	0.16	66	12.5	/
9	S3	1.5	8.8	-	-	-	-	-	-	-	-	-
10	S3	3.0	8.2	21.8	61.2	30.2	68.7	18.8	0.17	70	14.8	/
11	S4	0.5	8.1	19.5	31.1	27.1	65.6	20.7	0.16	68	11.1	/
12	S4	2.0	8.3	29.7	76.9	38.8	82.9	26.1	0.24	99	21.4	/
13	S4	3.0	7.3	-	-	-	-	-	-	-	7.3	-
14	S4	4.0	7.6	-	-	-	-	-	-	-	23.0	-
15	S5	0.5	8.6	20.2	61.9	27.4	62.6	18.5	0.17	73	11.8	/
16	S5	1.0	8.7	22.8	68.9	31.4	72.1	22.0	0.19	81	12.7	/
17	S5	6.0	8.1	-	-	-	-	-	-	-	-	-
18	S5	11.0	8.3	-	-	-	-	-	-	-	-	-
19	S6	0.5	8.1	16.5	54.4	23.2	56.7	17.7	0.13	61	9.6	/
19-1(19的 平行样)	S6	0.5	8.1	18.9	60.0	25.8	63.1	20.4	0.21	68	9.9	/
20	S6	2.0	8.4	21.3	66.2	29.3	64.5	19.8	0.16	77	12.2	/
21	S7	0.5	7.8	18.1	61.6	27.0	59.4	18.4	0.16	75	10.7	/
23	S7	3.0	7.5	-	-	-	-	-	-	-	-	-
24	S7	5.0	7.8	-	-	-	-	-	-	-	-	-
25	S8	0.5	8.2	22.2	62.6	26.5	70.7	21.8	0.17	77	10.7	/
27	S8	5.0	8.1	-	-	-	-	-	-	-	-	-
28	S8	7.0	8.1	-	-	-	-	-	-	-	-	-
29	S11	0.5	8.4	25.1	74.2	31.9	72.0	22.4	0.17	91	13.9	/
30	S11	2.0	8.7	35.0	94.8	43.8	94.6	30.0	0.27	125	20.0	/
31	S11	3.0		-	-	-	-	-	-	-	8.3	-
32	S12	0.5	9.0	21.3	66.4	29.3	70.5	20.6	0.14	85	11.6	/



检验检测报告

报告编号: SEP/SH1612339

客户名称: 中科院南京土壤研究所

联系人: 宋静

客户地址: 江苏省南京市北京东路71号

样品接收日期: 2016/12/30

提交报告日期: 2017/01/09



上海实朴检测技术服务有限公司